

STANDARDS UPDATE NOTICE (SUN) ISSUED: February 10, 2026

STANDARD INFORMATION

Standard: UL 1029

Standard ID: Standard For High-Intensity-Discharge Lamp Ballasts [UL 1029:1994 Ed.5+R:21Oct2024] **Previous Standard ID:** Standard For High-Intensity-Discharge Lamp Ballasts [UL 1029:1994 Ed.5+R:15Jul2022]

EFFECTIVE DATE OF NEW/REVISED REQUIREMENTS

Effective Date: October 21, 2026

IMPACT, OVERVIEW, AND ACTION REQUIRED

Impact Statement: Per our accreditation, Intertek is required to review reports against the standard revisions to confirm compliance. Once compliance is confirmed, the standard reference in the report is updated to show continued compliance to the technical requirements of the standard. Reports not updated to this version by the effective date above will be withdrawn.

Overview of Changes:

- Risk of Electric Shock During Relamping
- Requirements for Electronic High- Intensity-Discharge Lamp Ballasts

Specific details of new/revised requirements are found in table below

Current Listings Not Active? – Please immediately identify any current Listing Reports or products that are no longer active and should be removed from our records. We will do this at no charge as long as Intertek is notified in writing prior to the review of your reports.



STANDARD INFORMATION

CLAUSE	VERDICT	COMMENT
		Additions to existing requirements are <u>underlined</u> and deletions are shown lined out below.
27B		New section added;
		Risk of Electric Shock During Relamping
		HID lamp ballasts employing double-ended HID lamps shall comply with this test.
		See standard for details.
Supplement SB		New section added;
		REQUIREMENTS FOR ELECTRONIC HIGH-INTENSITYDISCHARGE LAMP BALLASTS
		These requirements cover electronic HID lamp ballasts including low frequency square-wave HID lamp ballasts and high frequency HID lamp ballasts.
		See standard for details.